



# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management Solid Waste Section

<b>UNIT TYPE:</b>												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<b>X</b>	<b>COUNTY:</b> Randolph <b>PERMIT NO.:</b> SLAS 76-05 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 2/28/2013

**Date of Last Inspection:** 11/16/2012

**FACILITY NAME AND ADDRESS:**

Cheek Plumbing & Backhoe  
 7748 Lanes Mill Road  
 Bennett, NC 27208

**GPS COORDINATES:** N: 35.6250 W: -79.57194

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Randy Cheek  
 Telephone: (336) 879-3764  
 Email address: N/A  
 Fax: (336) 879-5308

**FACILITY CONTACT ADDRESS:**

N/A

**PARTICIPANTS:**

Connie Wylie

**STATUS OF PERMIT:**

Active

**PURPOSE OF SITE VISIT:**

Routine

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

- Immediately schedule** a site visit with your extension agent/regional agronomist for an evaluation & advice concerning weed control/seeding during the spring months – particularly for field 2. Please **provide this office** with the written evaluation & any needed corrective actions from the agent/agronomist.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. Did not drive over entire site due to recent heavy rains. It appears that the approved setbacks are being met & field markers are adequate.
2. Noted some ruts on the front of field 2 – please repair.
3. The required signs are posted at both entrances and the access roads are adequate.
4. Both fields are currently harvested. Noted weeds & other vegetation on the fields, particularly the front section of field 2. Cattle were on field 3.
5. No apparent sign of recent application. No odors noted.

Please contact me if you have any questions or concerns regarding this inspection report.



\_\_\_\_\_  
Connie S. Wylie  
***Regional Representative***

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	<b>X</b>	US Mail		Certified No. <u>  </u>
----------	--	-------	--	---------------	----------	---------	--	-------------------------